


System: Pressure Manatee
Lines: 1-5, (400')
0.3 Soil LTAR
30' Trench Bottom
Accepted Status System
Repair: Pressure Manifold
Lines 6-11, (400')
0.3 Soil LTAR
24' Trench Bottom
Accepted Status System

System: 


Repair: 



- *Keep Tanks and Drain lines 10' from property lines.
- *Not a Survey
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicated above.

Central Carolina
Soil Consulting
919-569-6704
Project # 1497

SUBJECT PROPERTY IS _____ IS NOT ☒ LOCATED IN A SPECIAL FLOOD HAZARD AREA AS DESIGNATED ON FEDERAL EMERGENCY MANAGEMENT AGENCY (F.E.M.A.) FLOOD INSURANCE RATE MAP
 NUMBER 3720181300K ZONE X



ALL BEARINGS AND DISTANCES
 ARE CORRECT FIELD MEASUREMENTS

HAWTHORNE II, LLC - PHASE 2A
 SHEET 1 OF 2

PIN# 181300290361
 FIELD CLOSURE 1:23,881

NOT FOR RECORDING, INFORMATION FOUND
 THIS SURVEY WAS DONE WITHOUT THE BENEFIT OF
 A TITLE SEARCH AND IS SUBJECT TO ANY FACTS
 WHICH MAY BE DISCLOSED BY A FULL AND ACCURATE
 TITLE SEARCH

LEGEND
 EIP EXISTING IRON PIPE
 NIP NEW IRON PIPE
 MON MONUMENT
 PK PARKER KALON NAIL
 C.B. CATCH BASIN
 MH MANHOLE
 PP POWER POLE
 R/W RIGHT OF WAY
 C/L CENTER LINE
 FES FLARED END SECTION

LOT 134 BLOCK _____
 RECORDED IN PLAT BOOK 37 PAGE 30 GRANVILLE COUNTY, N.C.

I, JOHN Y. PHELPS, JR. HEREBY CERTIFY THAT THIS MAP IS
 CORRECT AND THAT THE BUILDINGS LIE WHOLLY WITHIN THE LOT
 AND THAT THERE ARE NO ENCROACHMENTS OF OTHER ADJACENT
 BUILDINGS ON SAID LOT UNLESS SHOWN OTHERWISE
 THIS MAP IS NOT FOR RECORDING.

PROPERTY OF
HOMESTEAD BUILDING CO.

688 WILLARD DRIVE
 BRASSFIELD TWP, GRANVILLE CO., NC

JOHN Y. PHELPS, JR.
 PROFESSIONAL LAND SURVEYOR
 5110 BUR OAK CIRCLE
 RALEIGH, NORTH CAROLINA, 27612 (919) 787-3658

SEAL
 1-13-14
 LAND SURVEYOR
 JOHN Y. PHELPS, JR. PLS # 1319

DATE 12/15/14
 1410
 84941