

++SEPTIC PUMPED MAY 2026++

The following photo log and inspection dissertation provide visual and procedural inspection information at the time of the inspection. Please skip to the conclusion in the report to see any repairs and/or suggestions that may be recommended.

PHOTO LOG:

Septic System Tank Locations



Inlet Chamber location shown



Home shown encroaching on septic tank



Inlet chamber lid handle shown broken



Inlet chamber shown open for inspection



Inlet drain pipe shown



Outlet chamber location shown



Outlet chamber shown open for inspection



Crack shown on backside of septic tank



Normal effluent level shown



Pump chamber location shown



Pump chamber riser lid shown broken



Pump chamber riser shown with crack



Driveway shown encroaching on pump tank. Supply line shown going towards driveway



Pump chamber shown open for inspection



Pump float noted as not being properly attached to float tree



Pump chamber electrical junction box shown inside of pump chamber. Conduit not sealed



Suspected area of drain field shown

