



ECONOMY EXTERMINATORS

P.O. BOX 4493 • CARY, NC 27519
Cary: (919) 362-1000 • Charlotte: (704) 847-8088
Wilmington: (910) 790-2000

- ☐ Termite Renewal Inspection
- ☒ Sentricon Renewal Inspection
- ☐ Dehumidifier Service Inspection
- ☐ Sump Pump Service Inspection

Page 1 of 1

Owner's Name(s) Jennifer Hedge Cust. # 39498

Property Address 1003 Inglenook Pl Apt NC 27502

Structure(s) Inspected: A. Main Residence Only ☒ B. Other ☐

Areas of the property which are deemed to be obstructed or inaccessible: Subfloor (insulation)

Garage (stuck beams) See Reverse

Note: Certain areas of all structures are obstructed or inaccessible (see reverse side for conditions governing this report)

☒ Please call office to schedule follow-up inspection, (at no charge) (Area Garage if 100% cleared; Attic)

Areas inspected: Crawlspace - Outside - Garage - Attic - Inside slab areas - Storage

Other _____

Inspection revealed visible evidence of: Subterranean termites

- ☒ Preventive original treatment; with no apparent termite infestation.
- ☐ Visible evidence of a previously treated infestation, which now appears to be inactive.
- ☐ Evidence of termites. We will be back on _____ at _____ to retreat at no charge.
- ☐ See Comments. Call us with any questions.
- ☐ See comments.

Circle if any evidence exists: Powder Post Beetles Wood Borers Fungi Other

☐ No evidence of these pests ☒ Visible evidence which appears to be inactive ☐ Evidence of / Needs Attention

If there is evidence of a previous or an active infestation of subterranean termites and/or wood-destroying insects in the wooden members, it must be assumed that there is some damage to the wooden members caused by this infestation, no matter how slight. If this is the case, the structural integrity of this property should be evaluated by a qualified building expert. (For the purpose of completing the report "infestation" means evidence of past or present activity by a wood-destroying insect visible in, on, or under a structure, or in or on debris under the structure) See conditions governing this report on the reverse.

Moisture Reading 12-13 % (Circle Yes or No) Conditions conducive to infestation: Yes No Standing Water: Yes No

Any new structural changes (additions, etc.): Yes No Update Graph? Yes No Stucco present on structure: Yes No

Was there visible evidence of damage? Yes No Was there activity in the Sentricon Stations? Yes N/A No (See comments)

Comments: Good Morning

There appears to be no termite activity at this time. I replaced 5 baits in stations today. Non-wood decaying fungi was noted on sub floor.

Thank you for choosing Economy. Please contact the office, Any questions

Inspector: Paul Eakes Date: 1/9/26
Print Name

Conditions Governing This Report

1. This report is based on observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and in some cases actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
2. This inspection and report are made on the basis of what was visible at the time of the inspection. An opinion is not given on areas that were enclosed or not readily accessible; finished areas of ground level rooms (basement and split level), areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes. All crawl spaces that have insulation are deemed to be obstructed above insulation line.
3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas are not considered to be readily accessible.
4. If there is evidence of infestation or infestation noted - There is possible hidden damage in structure.
5. If your structure has insulation in crawl space, your sub floor is deemed inaccessible.
6. This inspection was conducted for visible evidence of wood destroying pests. Mold is not a wood destroying pest as defined by the National Pest Management Association (NPMA). In addition we are not trained in determining nor recognizing the presence of health related molds. If you want your property inspected for the presence of these molds or related conditions contact the Public Health Department or an appropriately trained Certified Industrial Hygienist.

Legend

TE -	Termite Evidence	WBE -	Wood Borer Evidence	CD -	Cellulose Debris in Crawl Space
TX -	Termite Damage	WBX -	Wood Borer Damage	MCS -	Moist Crawl Space Area
PPBE -	Powder Post Beetle Evidence	FE -	Fungi (Moisture) Evidence	SW -	Standing Water in Crawl Space
PPBX -	Powder Post Beetle Damage	FX -	Fungi (Moisture) Damage	EW -	Earth Wood Contact
		O -	Other _____	IV -	Insufficient Ventilation
Organisms: Termites, Powder Post Beetles, Fungi, Old House Borers, Wood Borers				FG -	Faulty Grades
				IA -	Inaccessible Area