



Job #39875

Septic Blue Inspection Form NC

SEPTIC INSPECTION FORM

Date 2021-04-07	Customer Name James Newton
Service Address 31 Grist Mill Drive, Franklinton, NC, 27525	SECTION 1 Are there any state or local requirements regarding the evaluation of a septic system? NO
SECTION 2 Does this evaluation / inspection meet the requirements of state and local agencies? N/A	SECTION 3 Location of system: LEFT SIDE
SECTION 4 Septic tank distance from foundation in feet. 10	SECTION 5 Estimated size of tank: 1000
SECTION 6 What is the separation between the septic system and the well or state /county body of water 1000	SECTION 7 DOES THE SEPARATION OF THE SEPTIC SYSTEM AND WELL/BODY OF WATER MEET LOCAL REQUIREMENTS? N/A
SECTION 8 Any evidence of malfunction? (Please check all applicable observed conditions) ☒ NO EVIDENCE OF MALFUNCTION	SECTION 9 Is system working properly? yes
IF TANK IS BEING OPENED AND PUMPED , PLEASE ANSWER THE FOLLOWING QUESTIONS: -	SECTION 10 Septic tank material: Concrete
SECTION 11 Liquid level in tank Normal	SECTION 12 Does the Septic tank have a baffled wall? Yes

SECTION 13 Flushing to the tank ? Yes	SECTION 14 Condition of the baffles and / or sanitary tees: Good
SECTION 15 Inlet baffle or "T" None present	SECTION 16 Outlet baffle or "T" Present and functional
SECTION 17 Tank was pumped? Yes	SECTION 18 Is tank adequately sized for the # of bedrooms ? Yes
SECTION 19 The number of bedrooms? 3	SECTION 20 Is the tank adequately sized for # of occupants? Yes
SECTION 21 The number of occupants? 4	SECTION 22 System working properly? YES
SECTION 23 Last know pump years? 7	COMMENTS: Tree roots were removed.

Customer Acceptance:

Septic systems are subterranean; therefore , it is impossible to determine their overall condition , unless excavated . Also when no water is entering the field lines , IE. if the house is vacant , a determination of their status is difficult. No prediction can be made as to when or if a system might fail. This report comments on the work-ability of the system on the day of the inspection only, and is in no way intended to be a warranty. Work-ability can alter by factors such as excessive rain fall , heavy water usage, faulty plumbing, neglect or physical damage to the system. This report cannot be used for real estate transactions in the state of North Carolina. All tanks require pumping maintenance.

On File