



- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.
- *No adding soil within septic area
- *No rutting-up septic area
- *No cuts of >2' within 15' of septic areas

System: -----
 Repair: —————
 [ST] = 1250 gallon tank with risers
 (#2) = profile description locations

GRAPHIC SCALE
 1" = 40'



Initial System: Gravity to Serial
 Lines: 1-5, (515')
 Accepted Status System (25% reduction)
 0.3 Soil LTAR
 30" Trench Bottom on the downhill side
 Repair System: Pressure Manifold
 Lines: 6-10, (400')
 T&J Panel Block System (vertical)
 0.3 Soil LTAR
 30" Trench Bottom on the downhill side



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

5-Bedroom Septic Layout
 Lot 11, Maison Ridge Subdivision
 Franklin County, North Carolina

Job#: 4862
 Drawn By: JR
 Date: 04/17/2025
 Revision: