

Heritage Remodel and
Design
5003-H Falls of Neuse Rd
Raleigh, NC 27609
Lic. # 21209

August 27, 2026

Phil Layton
1014 Country Ridge Dr.
Raleigh, NC 27609

- 1- The exterior receptacle under carport does not need a cover due to the NEC code it's beyond 5ft horizontal rule for rain
- 2- Installed blank covers where needed in crawl space
- 3- Installed GFCI in kitchen where needed to protect receptacle by sink
- 4- Lights in kitchen are not loose; it's way the lights are made. Trims are magnetic
- 5- Made repair to receptacle in office
- 6- Installed panel screw in on panel and replace one screw in other panel with proper panel screw
- 7- Replaced cover at front of house on left exterior receptacle with a new bubble cover
- 8- The GFCI on front of house to the right on exterior works, it works on a switch inside the house

Buddie Quinn
Electrician
Lic# 21209