

**EMSL Analytical, Inc.**

2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

<http://www.emsl.com>raleighlab@emsl.com

EMSL Order: 291204398
CustomerID: MISC-ACCT
CustomerPO:
ProjectID:

Attn: _____

**14928 Creedmoor Road
Wake Forest, NC 27587**

Phone: (919) 671-9004
Fax:
Received: 08/30/12 9:20 AM
Analysis Date: 8/31/2012
Collected:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos	
			% Fibrous	% Non-Fibrous	% Type	
1	Ceiling Tile	Brown/White	90% Cellulose	10% Non-fibrous (other)	None Detected	☒
291204398-0001		Fibrous Heterogeneous				



No Asbestos Detected

Between Expected Limit of Detection and
Federal EPA Recommended Limit

Above Federal EPA Recommended Limit

These guidance limits are typically used in most scenarios. More stringent local or project specific guidelines may apply.

Analyst(s)

Billy Barnes (1)

Essie Spencer, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296

Initial report from 08/31/2012 11:02:59