
Re: Structure Inspection Acknowledgment @ 8337 Tie Stone Way

From Info <info@cfr-nc.com>

Date Mon 9/14/2026 4:10 PM

To Mitra Ahdieh <Mitra.Ahdieh@longandfoster.com>

Correct in my opinion the control separations looked normal and didn't need any repairs at the time.

Thanks,

Jonathan Hallenborg
Cornerstone Foundation Repair
919-599-6687

From: Mitra Ahdieh <Mitra.Ahdieh@longandfoster.com>

Sent: Monday, 14 September 2026 15:41:54

To: Info <info@cfr-nc.com>

Subject: Structure Inspection Acknowledgment @ 8337 Tie Stone Way

Hi John,

First, thank you for inspecting the small crack on the living room floor, as well as, the crack on the left side of the outside of the house at 8337 Tie Stone Way on August 4, 2026. You reported back to me on August 17th that no structural repairs were required, and that the living room floor crack could be filled and the new floor laid. The work inside the house has been completed as of August 25th. I will be disclosing this information as part of the MLS listing. Appreciate if you could review the attached photos and reply to this email, per our phone conversation today, acknowledging the inspection and review of the pictures. Thank you!

Mitra Ahdieh
Real Estate Broker
Long & Foster Real Estate
mitra.ahdieh@longandfoster.com
(919) 608-0906

The contents of this e-mail message may be privileged and/or confidential. If you are not the intended recipient, any review, dissemination, copying, distribution or other use of the contents of this message or any attachment by you is strictly prohibited. If you receive this communication in error, please notify us immediately by return e-mail, and please delete this message and all attachments from your system.

Warning: If you receive an email from anyone concerning a transaction involving our company which

requests that you wire funds or that you provide nonpublic personal information by unsecured return email, do not respond to the message. To protect yourself, immediately call our company.
