

**CERTIFICATE OF OCCUPANCY
PERMANENT**

RYAN HOMES
3737 GLENWOOD AVE STE 10
RALEIGH, NC 27612

Certificate number 12-00001097

Issue Date.....December 08, 2011

Property Address.....1108 RIGGINS MILL RD

Subdivision Name.....Hilliard Forest Subdivision

Contractor.....RYAN HOMES
(919)573-6055

Description of work.....BLDG- NEW SNGL FAM DETACHED

Occupancy type: RESIDENTIAL(IBC SEC 310)

This is to certify that all required building code inspections have been completed on this structure and all known code violations discovered during such inspections have been duly noted, ordered corrected and have been reinspected. As a result of the inspections made, work performed under this permit has been found to be in substantial compliance with the applicable building codes. This complies with North Carolina General Statute 160A-423.

This Certificate does not replace any license required by law, nor does It authorize any use other than occupancy. Any change in occupancy from that hereinabove described of this structure shall require a new Certificate of Occupancy.

CERTIFICATE OF OCCUPANCY PERMANENT

WINSLOW PROPERTIES DEVELOPMENT
740 LOCH HIGHLANDS DR
RALEIGH, NC 27606

Certificate number 12-00001097

Issue Date.....December 08, 2011

Property Address.....1108 RIGGINS MILL RD

Subdivision Name.....Hilliard Forest Subdivision

Contractor.....RYAN HOMES
(919)573-6055

Description of work.....BLDG- NEW SNGL FAM DETACHED

Occupancy type: RESIDENTIAL(IBC SEC 310)

This is to certify that all required building code inspections have been completed on this structure and all known code violations discovered during such inspections have been duly noted, ordered corrected and have been reinspected. As a result of the inspections made, work performed under this permit has been found to be in substantial compliance with the applicable building codes. This complies with North Carolina General Statute 160A-423.

This Certificate does not replace any license required by law, nor does It authorize any use other than occupancy. Any change in occupancy from that hereinabove described of this structure shall require a new Certificate of Occupancy.