

AIR FLOW SERVICES LLC
704 SUMMER MUSIC LN
RALEIGH,27603
919-339-6856

INVOICE

Invoice# 7218

Bill To: Jennifer Johnson
Pragya Agrawal
205 Bethabara Ln
Cary,27513

Invoice Date : 8/23/2026
Due Date : 8/23/2026

#	Item Details	Qty	Rate	Amount
1	6 feet line set 3/4 and 3/8	1	650	650.00
2	Maintain 2 outside system	1	110	110.00
3	R410A refrigerant	3	80	240.00
4	Labor and MISC	1	250	250.00
			Sub Total	1250.00
			Total	\$1250.00

No

After checking pressure found system low on refrigerant, also after reviewing the inspector report , was an oily spot in the crawl space under line, found oily spot due to leaking refrigerant on the line set, remove couple feet from line set 3/4 and 3/8 and replaced with new one, after braizing and sealed line set put the nitrogen to make sure no leak, also put the system under vacuum, tight line set and left it away from ground, added about 3 lbs of r410 refrigerant to balance pressure level, maintain 2 condenser . turn system and checked sequence of operation..

thERFORMED Terms & Conditions

Customer

SIGNATUR :

TECH

SINATURE :