

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.
- *No adding soil within septic area
- *No rutting-up septic area
- *No cuts of >2' within 15' of septic areas

System: ---
Repair: —

PROP.
CONSTRUCTION
ENTRANCE

PROP. SILT
FENCE (TYP.)

LOD = 0.55 AC

Initial System: Gravity to Serial Dist.
Lines: 1-5, (440')
Accepted Status System
0.3 Soil LTAR
24" Trench Bottom on downhill side

Repair System: Gravity to Serial Dist.
Lines: 6-11, (274')
T&J Panel Block System (horizontal)
0.3 Soil LTAR
24" Trench Bottom on downhill side

GRAPHIC SCALE
1" = 40'



Central Carolina Soil Consulting, PLLC
1900 South Main Street, Suite 110
Wake Forest, North Carolina 27587
Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
Lot 35, Carriage Farm Subdivision
Wake County, North Carolina

Job#: 5353
Drawn By: JR & PC
Date: 11/20/2025
Revision: