

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363

Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

December 5, 2017

Jeffrey Ruggiero
301-639-9447
8121 Owenston Court
Raleigh, NC

E-mailed to: jefferymruggiero@gmail.com

RE: Engineering - Field Observation
8121 Owenston Court ; Raleigh, NC
Project No.: 17DDM-1205A

To Whom It May Concern/Inspections Dept.:

The undersigned arrived on-site previously 12-5-17 to observe, measure and analyze the following for the above referenced site:

The cracks in the basement wall approximately 10 feet back of the front left corner along the left side was observed. The crack appears to be small and is in the area of a discontinuous load path (cantilevered fireplace). The crack appears to be cosmetic and not structural as the areas on the outside and above the area on the inside show no structural distress.

Sincerely,

David Miller, PE

DEM/17DDM-1205A

