



Comfort Hounds Heating & Cooling

Sarah Calvert
6600 Westborough Drive
Raleigh, NC 27612

(704) 962-0172
safracal@gmail.com

JOB	#3515
SERVICE DATE	Nov 20, 2023
PAYMENT TERMS	Upon receipt
DUE DATE	Nov 20, 2023
AMOUNT DUE	\$0.00

CONTACT US

1008 Fieldgrass Pl
Raleigh, NC 27603

(919) 578-7798
info@mycomforthounds.com

INVOICE

Services	qty	unit price	amount
Comfort Club - Maintenance & Inspection Performed Heating Maintenance & Inspection Checked & inspected complete operation in the heating mode checked & Inspected electrical connections, controls, and components Checked & Inspected mechanical moving parts Checked & inspected furnace heat exchanger - ok Checked filter condition - ok Checked for gas leaks in and around furnace - No leaks Checked carbon monoxide levels - ok The systems are operating at this time. The blower motor capacitor is low and outside manufacturer specifications and should be replaced. The blower fan has debris build-up which is reducing air quality and air flow. This component is recommended to be chemically cleaned. The customer has agreed to these repairs.	1.0	\$0.00	\$0.00
Heating / Furnace - We Get The Heat On - Residential - Heating Service Call Arrived to find the furnace not lighting due to the Inducer fan motor not operating. I got the fan unstuck and running temporarily but it makes loud noises and improper airflow. It is recommended that the Inducer fan assembly be replaced and the unit given Maintenance. The customer has signed up for the Comfort Club Maintenance plan and agreed to having the motor replaced.	1.0	\$87.00	\$87.00
HD1000 Draft Inducer Assembly 80% System Service Repair - Club Pricing Disconnected the motor electronics. Removed the old Inducer motor assembly. Cleaned the assembly motor area. Installed the new motor assembly. Connected the electrical connections. Tested the furnace.	1.0	\$674.14	\$674.14
A140U Fan/Blower Capacitor Installation Repair Service - Single Replaced the faulty blower motor capacitor.	1.0	\$143.01	\$143.01
M104C Cleaning of Blower Motor assembly, Includes Blower Cabinet - Club Pricing Disconnected the blower motor electronics. Pulled out the blower motor assembly. Removed the blower motor from the blower assembly. Chemically cleaned the blower wheel and cabinet. Reattached the blower motor. Reinstalled the blower motor assembly. Reconnected the blower motor electronics.	1.0	\$372.30	\$372.30

Services subtotal: \$1,276.45

Subtotal **\$1,276.45**

Total Tax	\$86.24
Wake County (7.25%)	\$86.24
Job Total	\$1,362.69
Amount Due	\$0.00

Payment History			
Nov 20	Mon 6:45pm	Credit Card	\$1,362.69

Thank you for choosing Comfort Hounds Heating & Cooling!

Making A Comfortable Difference

Cancellations for service calls must be at least 4 hours before service or a \$47.00 cancellation/no-show fee will be applied and due upon receipt. All invoices can be paid online via the link on the invoice email.

See our [Terms & Conditions](#)