On-site Wastewater Inspection

✓ Pre-Inspection Contract, signed by Client is attached to Inspection

Property Address: 3833 Jonesville Rd., Wake Forest, NC 27587

Client Name: Craig Worrell

Current owner of Record: Uknown

Date of Inspection: 10/19/2026

3BR Advertised number of bedrooms as stated in MLS or as stated in attached sworn statement by owner or owner's representative

360 Gallons per day for designed system size or number of bedrooms as stated in available local health department information

✓ Inspection shall include any part of the system located more than 5 feet from the primary structure that is a part of the operations permit

N/A Copy of Operations permit from WAKE County Environmental Health Attached

✓ Operations permit not available

NO System requires a certified subsurface water pollution control system operator pursuant to G.S. 90A-44

Current Operator's Name _____

Most recent performance, operation and maintenance reports are ____attached ____not available

Type of water supply X Well ____ Public Water ____Community Water ____Spring

Location of Septic Tank and septic tank details:

15 ft from house or structure

100 ft from well if applicable

UkN ft from water line if applicable

UkN ft. from property line if said property lines are known or marked Property lines not marked

UkN distance from finished grade to top of tank or access riser

Yes Access riser(s) yes no Describe Metal pipe, open + no lid

NO Tank lids intact yes no

NO Tank has baffle wall yes no Describe condition of baffle wall: _____

UkN Inflow to tank is noted as sufficient

UkN Inflow to tank is noted as insufficient or blocked

NO Water level in tank is relative to tank outlet

UkN Outlet T is present yes no Describe condition of Outlet T: _____

UkN Outlet has filter yes no Describe condition of filter: _____

UkN Effluent leaves the outlet yes no

Yes Roots present in tank yes no Describe extent of roots: Mats of roots in the tank

NO Evidence of tank leakage Describe: _____

NO Evidence of non-permitted connections, such as downspouts or sump pumps

Yes Connection present from house to tank

UkN Connection present from tank to next component

UkN Percentage of solids in tank

NO Unable to locate tank. System inspection cannot be completed until tank is located

Date tank was last pumped _____ unknown

Does system have pump tank? ✓ yes (complete blanks below) NO na

____ ft from house or structure

____ ft from well or spring if applicable

____ ft from water line if applicable

____ ft. from property line if property lines are known or marked

____ Distance from finished grade to top of tank or access riser

Pump Tank Observations Continued:

____ Access risers in place yes no

____ ft from septic tank

____ Access risers in place Describe type: _____

____ Describe condition of tank lids _____

Location of control panel: _____

____ Electrical connections are in place and properly grounded

____ Audible and visible alarms (as applicable) work

____ Pump turns on and effluent is delivered to next component

____ Unable to operate pump due to lack of electricity at site at time of inspection

Dispersal field: Type of system: X Conventional ___Accepted ___Innovative ___Experimental __Controlled Demonstration ___Pretreatment; Type of pretreatment _____

Brief Description of System Type II A

UkN ft. from property line if property lines are known or marked

UkN ft from septic/pump tank

UkN # of lines

UkN length of lines

NO Evidence of past or current surfacing at time of inspection

Briefly describe: _____

NO Evidence of traffic over the dispersal field

~~Unk~~ Yes Vegetation, grading and drainage noted that may affect the condition of the system or system components

UkN Effluent is reaching the dispersal field

Yes Conditions present that prevented or hindered the inspection

Yes Adverse conditions present that require repair or subsequent observation or warrants further evaluation by the local health department. Description of adverse condition: The tank is collapsing + full of roots

Consequences of the adverse condition: The tank will collapse leaving a open hole which is a saftey hazard.