MASSEY SERVICES INC.®

Inspection Graph

DATE 10/16

NAME Vanessa Moore ADDRESS 307 Dobbs Ct Elsberry

HOME PHONE 252 883-5831 BUSINESS PHONE _____ EMAIL _____

PERIMETER MEASUREMENT 174 ARE THERE AREAS OF ACTIVE OR PREVIOUS ACTIVITY? YES _____ NO X

WOOD DESTROYING INSECT KEY
ST = Subterranean termites
DT = Drywood termites
FT = Formosan termites
PPB - Powder post beetles
WB = Wood borers
Other_____

DAMAGE/INFESTATION
XXX = Existing damage
A = Active Insects
SD = Suspected damage

CONSTRUCTION KEY
Foundation Type:
☐ Slab
☑ Crawl space
☐ Basement
☐ Other_____

Siding Type:
☐ Wood
☐ Brick/Stone
☐ Stucco
☐ Vinyl
☐ Other_____


STRUCTURAL USE
☐ Residence
☐ Commercial
☐ Multi-Family
☐ Detached Garage/Shed
☐ Other_____

TREATMENT KEY
O = Approximate Location of Bait Stations
TT = Trench and treat soil
IT = Interior treatment
• • • • = Areas to be drilled

STRUCTURES TO BE TREATED
☐ Main House/Building
☐ Detached Garage/Shed
☐ Other_____

MOISTURE CONDITIONS
☐ Irrigation hitting wall
☐ No gutters/blocked gutters
☐ Plants too close to wall
☐ Plumbing/roof leaks
☐ Moisture staining
☐ Improper drainage
☐ Other_____

Scale: 1 square = _____ft.



IMPORTANT NOTICE FOR ALL SERVICE TYPES

INSPECTOR: Billy GM: _____ CUSTOMER SIGNATURE: Vanessa Moore

The following areas of your property have damages that pre-existed at the time of this inspection. If the damaged areas are not repaired, these areas will be excluded from the repair or replacement guarantees outlined in the corresonding service agreements.

Massey cannot guarantee that the wood destroying organism damage disclosed by visual inspection represents the entirety of the damage which may exist on the date of this inspection. Therefore, Massey will not be responsible for the repair of any damage which exists in areas or in structural members which are concealed or inaccessible by visual inspection on the date of this inspection.

MS-051NC (6/21)

SERVICE COPY