



System: Gravity to Serial
Lines: 6-8, (440')
Accepted Status System
0.275 Soil LTAR
22" Trench Bottom

Repair: Pressure Manifold
Lines: 1-5, (460')
Accepted Status System
0.3 Soil LTAR
22" Trench Bottom

System: ---
Repair: ---
Boring: ●
ST 1000 Gallon

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines > 5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



Central Carolina Soil Consulting, PLLC
1900 South Main Street, Suite 110
Wake Forest, North Carolina 27587
Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
Lot 30, Watson Ridge Subdivision
Franklin County, North Carolina

Job# : 4862
Drawn By : MS
Date : 08/23/2024
Revision: