



Job #55905

Septic Blue of NC Inspection Form

SEPTIC INSPECTION FORM	
Date 2023-05-17	Customer Name Ginger Williams
Service Address 355 Windsong Ln., Youngsville, NC 27596	SECTION 1 Are there any state or local requirements regarding the evaluation of a septic system? NO
SECTION 2 Does this evaluation / inspection meet the requirements of state and local agencies? YES	SECTION 3 DOES THE SEPARATION OF THE SEPTIC SYSTEM AND WELL/BODY OF WATER MEET LOCAL REQUIREMENTS? YES
SECTION 4 What is the separation between the septic system and the well or state /county body of water Over 100 ft.	SECTION 5 Is system working properly? yes
SECTION 6 Any evidence of malfunction? (Please check all applicable observed conditions) ☒ NO EVIDENCE OF MALFUNCTION	SECTION 7 Location of system: BACK
SECTION 8 Septic tank distance from foundation in feet. 15	SECTION 9 Estimated size of tank: 1000
SECTION 10 Septic tank material: Concrete	SECTION 11 Liquid level in tank Normal
SECTION 12 Does the Septic tank have a baffled wall? Yes	SECTION 13 Flushing to the tank ? Yes
SECTION 14 Condition of the baffles and / or sanitary tees: Satisfactory	SECTION 15 Inlet baffle or "T" None present

SECTION 16 Outlet baffle or "T" Present and functional	SECTION 17 Tank was pumped? Yes
Section 18 Distribution Box No	D. Box Distribution Box has solid buildup? -
D. Box Are there any structural damages to the Distribution Box such as deterioration or cracks? -	D. Box Distribution Box Effluent has equal distribution? -
D. Box How Many Drainfield lines leave the Distribution Box? -	D. Box Are all drainfield lines leaving the box draining properly? -
SECTION 19 Occupancy The number of bedrooms? 3	SECTION 20 Is tank adequately sized for the # of bedrooms ? Yes
SECTION 21 Is the tank adequately sized for # of occupants? Yes	SECTION 22 The number of occupants? 1
SECTION 23 System working properly? YES	SECTION 24 Last know pump years? 8
COMMENTS: Recommend customer having tank pumped out along with a bacteria treatment every three years as well as cleaning filter every 6 to 12 months	

Customer Acceptance:

Septic systems are subterranean; therefore , it is impossible to determine their overall condition , unless excavated . Also when no water is entering the field lines , IE. if the house is vacant , a determination of their status is difficult. No prediction can be made as to when or if a system might fail. This report comments on the work-ability of the system on the day of the inspection only, and is in no way intended to be a warranty. Work-ability can alter by factors such as excessive rain fall , heavy water usage, faulty plumbing, neglect or physical damage to the system. This report cannot be used for real estate transactions in the state of North Carolina. All tanks require pumping maintenance.