



A&S Pest Control, Inc
PO Box 755
Norlina, NC 27563
(252) 456-2362

Attn: Carl & Jill Pike Triangle North Realty
Triangle North Realty
P.O. Box 850
Oxford, NC 27565

Invoice
305 Gilliam St.

INVOICE NO. ACCOUNT NUMBER

207226 112215

INVOICE DATE

05/27/2026

LICENSE

722PW

DUE DATE (NET 0 TERMS)

Upon Receipt

AMOUNT DUE

\$150.00

Triangle North Realty (Acct #: 39714)

ITEM	QUANTITY	PRICE	SUBTOTAL
WDIR - Main Residence	1	\$150.00	\$150.00

Additional Notes

Subtotals	\$150.00
Total	\$0.00
Discounts	
Taxes	\$0.00
Invoice Total	\$150.00
Amount Paid	\$0.00
Amount Due	\$150.00

THIS REPORT IS MADE IN ACCORDANCE WITH AND SUBJECT TO THE CONDITIONS ON THE REVERSE SIDE OF THIS PAGE
This is not a structural damage report. Neither is this a warranty as to the total absence of wood-destroying insects.

OFFICIAL NORTH CAROLINA WOOD-DESTROYING INSECT INFORMATION REPORT

This is to report that a qualified inspector employed by the below-named firm has carefully inspected readily accessible areas of the property located at the address below for wood-destroying insects. This report specifically excludes hidden areas and areas not readily accessible (see section 2 below) and the undersigned pest control operator has not made any inspection of such hidden areas or of such areas not readily accessible. This is **not a warranty as to the total absence of wood-destroying insects or damage from same**. This inspection described herein was made on the basis of visible evidence. This report is submitted without warranty, guarantee, or representation as to concealed evidence of infestation or damage or as to any future infestation.

1. Seller's Name(s) <u>Louisa Menick</u> Buyer's Name(s) _____ Address of Property <u>305 Gilliam St., Oxford, NC 27565</u> Structure(s) Inspected: A. Main Residence Only ☒ B. Other _____	
F I N D I N G S	
2. Areas of the property which are deemed to be obstructed or inaccessible: Note: Certain areas of all structures are obstructed or inaccessible (see numbers 2 & 3 on the reverse side for conditions governing this report). If there is evidence of a previous or an active infestation of subterranean termites and/or other wood-destroying insects in the wooden members, it must be assumed that there is some damage to the wooden members caused by this infestation, no matter how slight. If this is the case, the structural integrity of this property should be evaluated by a qualified building expert. (For the purpose of completing the report "infestation" means evidence of past or present activity by a wood-destroying insect visible in, on, or under a structure, or in or on debris under the structure.)	
3. Inspection revealed visible evidence of:	Location of visible evidence of infestation:
☒ A. Subterranean termites ☐ 1. Control measures were performed. ☐ 2. No control measures were performed. ☒ 3. Visible evidence of a previously treated infestation, which now appears to be inactive.	Termite damage in floor joists behind front porch (see graph)
☐ B. Powder post Beetles ☐ 1. Control measures were performed. ☐ 2. No control measures were performed. ☐ 3. An infestation which now appears to be inactive.	
☐ C. Old House Borers ☐ 1. Control measures were performed. ☐ 2. No control measures were performed. ☐ 3. An infestation, which now appears to be inactive.	
☐ D. Others _____ ☐ 1. Control measures were performed. ☐ 2. No control measures were performed. ☐ 3. An infestation which now appears to be inactive.	
☐ 4. No visible evidence of infestation from wood-destroying insects was observed.	
5. The following conditions conducive to subterranean termites were noted in this property:	

FIRM: A&S Pest Control, Inc

PCO Lic No.: 722PW

Date: 2026-05-27

Address: 281 US-1, Norlina, NC 27563

Telephone: (252) 456-2362

Signature of Authorized Company Rep: _____

Title: CPO

Purchaser's signature is required on reverse side.

OVER

CONDITIONS GOVERNING THIS REPORT

1. This report is based on observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and in some cases actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
2. This inspection and report are made on the basis of what was visible at the time of inspection. An opinion is not given on areas that were enclosed or not readily accessible: finished areas of ground level rooms (basement and split level); areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes.
3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas are not considered to be readily accessible.
4. Detached garages, sheds, lean-tos, other buildings or fences on the property are not included in this inspection report unless specifically noted.
5. Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in this property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

REMARKS

This space should be used to clarify any statement made above.

IT IS THE RESPONSIBILITY OF THE CLOSING AGENT TO OBTAIN PROPER SIGNATURES

Signature: _____ Date Acknowledged: 2026-05-27

Signature: _____

A&S Pest Control, Inc.
P.O. Box 755, Norlina, NC 27563
(252) 456-2362

OWNER

TREATING ADDRESS

305 Gilliam St

DATE

5/27/26

HOME PHONE NO.

INSPECTOR

T. Freeman


TARGET PEST

termites

BUSINESS PHONE NO.

INSPECTION GRAPH

Ratio:



Inspection Key:

- ☐ Subterranean Termites = T
- ☒ Existing Damage = X
- ☐ Carpenter Ants = CA
- ☐ Powder-Post Beetles = PPB

- ☐ Old House Borers = OHB
- ☐ Fungus = F
- ☐ Cellulose Debris = CD
- ☐ Carpenter Bees = CB
- ☐ Earth-Wood Contact = EC

- ☐ Moisture Reading = MR
- ☒ Previous Activity = PT
- ☐ Wood Bores = WB
- ☐ Inaccessible Areas = IA
- ☐ Possible Hidden Damage = PHD

Type of Construction: (check all that apply)

- ☐ Crawl Space
- ☐ Supported Slab
- ☐ Basement
- ☐ Piers Only
- ☐ Monolithic Slab
- ☐ Floating Slab

Type of Foundation: (check all that apply)

- ☐ Hollow Block
- ☐ Tile Block
- ☐ Single Brick
- ☐ Double Brick
- ☐ Triple Brick
- ☐ Brick Veneer
- ☐ Concrete
- ☐ Stone
- ☐ Other _____