

Ambassador Inspections
Brennan Smith
BrennanSmith2896@outlook.com
Brennan Smith: 984-255-3633
Robert Smith: 919-339-5633
PO Box 337
Bunn, NC 27508



This is the upper part of the leach field. The leach line on the right goes under the driveway.



This is the lower part of the leach field. There are trees in the leach field. There were no signs of surfacing in the leach field.