

GlobeSpec

07:59AM May 22, 2026

Photo Attachments



HS-9 (Pg 5): Bond at the manifold in the attic



HS-9 (Pg 5): Bond at the manifold in the attic



HS-9 (Pg 5): No visible bond at the exterior



HS-9 (Pg 5): No visible bond at the exterior