

City of Raleigh Fire Department Basic Fire Report**FDID:09213****Alarm Date:** 12-30-2023**Incident Number:** 23-0054586**Address:** 5919 Hourglass CT RALEIGH NC 27612

Dispatch Time: 03:21:25

Arrival Time: 03:26:50

Clear Time: 06:31:32

Narrative

Incident Type:Structure Fire Multiple Resid All units were dispatched to a structure fire. While enroute, headquarters advised that there were multiple calls and subjects were jumping from the residence. Upon arrival, E17 marked working fire and took command. E17 found heavy fire coming out of Division A front door, Division D roof, and Division C. E17 deployed a 1 ¾" line to division 1 for fire attack and found heavy fire conditions. E17 driver charged the line and found 2 patients outside across the street. E17 driver called E23 for assistance in patient care. L14 established vent and search group in division 1. E23 assisted E17 with hydrant connection. E23 deployed a second 1 ¾" line to division 2. B4 arrived, took command, and called for a second alarm. Staging was set up at station 17. R16 took primary search division 2. Division C was set up by B3, E18, and L4. RIT was set up by E16. DC1 arrived and took over command and B4 became operations. Exposures B and D were searched and checked for extension. All units were backed out for aerial operations. Units were sent back in for salvage and overhaul after aerial operations. Raleigh fire investigators preformed investigation. Units were rotated out and returned to service.

Classified:Unintentional[Print the Fire Report](#)