

**LISBON MAINTENANCE COMPANY**

1500 LISBON BRIDGE ROAD  
GARLAND, N. C.. 28441-8430

TELEPHONE: 910-529-1921

FAX: 910-529-1846

November 16, 2023

**CERTIFICATION of PERFORMANCE**

Donald Hoyle  
369 Dy Hoyle Lane  
Henderson, NC 27527

227 Willowood Drive  
Henderson, NC 27536

To Whom IT May Concern

- 1.00 Site survey made on the above location 11-14-23 Fill pipe and vent line removed.. Tank was completely empty of product.

A 560 heating oil tank was  
foam-filled to a 350 gram density. Tank openings were sealed  
with concrete.

Ground water table was below tank bottom.

- 2.00 UST closure by EPA approved foam. Tank closed in accordance with existing NCDENR requirements for heating oil tanks less than 1,000 gallons in size.  
Soil was of a heavy dark red clay. Ground water was below tank bottom

- 3.00 Lisbon Maintenance Management is 40 hours OSHA trained and certified.  
Also trained and certified for DOT handling and transporting of Hazardous material. Not responsible for underground utilities or structures not specified or located. Liability insurance limits of \$ 5,000,000 are included.

Lisbon Maintenance Company



Norwood S. Carter, President  
TCA No. 0090