



Air Works Heating & Air, Inc.
5100 Unicon Dr.
Unit 107
Wake Forest, NC 27587

Phone: (919) 528-4333
Fax: (919) 964-3266
service@airworksnc.com
www.airworksnc.com

Bill to
Audrey Higgins
110 Sorrel Dr.
Franklinton, NC 27525

Ship to
Audrey Higgins
110 Sorrel Dr.
Franklinton, NC 27525

Work Order #: 23962

Transaction Date: 7/30/2024

Terms: Due on receipt

Invoice #: i23194

Item	Description	Quantity	Price	Amount
20-2 Duct Cleaning 1,000-1,599	Clean ducts on system 1,000 - 1,599 Square Foot.	1	\$599.00	\$599.00
20-20 2nd Sys Clean 1001-1599	Clean ducts on additional system 1,001 - 1,599 Square Foot.	1	\$450.00	\$450.00
21-3 Clean Dryer Vent w/Duct Cl	Clean Dryer vent with Duct Cleaning.	1	\$99.00	\$99.00
0-1N	I arrived at 110 Sorrel Dr in Franklinton and performed a Duct cleaning on a two system house. I cleaned each vent and one return upstairs, then proceeded to clean out all of the flexes, the supply box and the return box located in the attic. I then attached everything to the downstairs system and cleaned each vent and one return on the first floor. I also cleaned out all of the flexes, the supply box and the return box located in the crawlspace. The customer also agreed to a dryer vent cleaning. Before the cleaning the dryer vent was reading 492 CFM's and after the cleaning the dryer vent is now reading 1417 CFM's. Before and after pictures will be attached in email. Thank you- Axl	1	\$0.00	\$0.00

You could have saved \$172.20



Subtotal:	\$1,148.00
Tax:	\$0.00
Total:	\$1,148.00
Payments:	\$1,148.00
Balance Due:	\$0.00



Air Works Heating & Air, Inc.
5100 Unicon Dr.
Unit 107
Wake Forest, NC 27587

Phone: (919) 528-4333
Fax: (919) 964-3266
service@airworksnc.com
www.airworksnc.com

Acceptance

* All parts and labor furnished by Air Works Heating & Air are warranted for one (1) year from the date of service. * Air Works warrants that all work will be completed in a workmanlike manner. Air Works is not responsible for the current condition of Customer's property (ie., existing wiring, thermostats, pipes, etc.).* If a check is returned for insufficient/uncollected funds or this invoice amount is not paid in full upon completion, Customer shall be responsible for all fees, collection costs, and reasonable attorney's fees incurred by Air Works in securing payment under this invoice. I hereby acknowledge the satisfactory completion of all services rendered, and agree to pay the cost of services as specified above.

A handwritten signature in black ink, appearing to read "Audrey Higgins", written over a horizontal line.

Audrey Higgins



Air Works Heating & Air, Inc.
5100 Unicon Dr.
Unit 107
Wake Forest, NC 27587

Phone: (919) 528-4333
Fax: (919) 964-3266
service@airworksnc.com
www.airworksnc.com

Attachments

1. [Dining Area Vent Before .jpg](#)
2. [Downstairs Return Box Before .jpg](#)
3. [Upstairs Return After .jpg](#)
4. [Master Bathroom Vent Before .jpg](#)
5. [Master Bedroom Vent After .jpg](#)
6. [Living Room Vent After.jpg](#)
7. [Upstairs Supply Box Before .jpg](#)
8. [Upstairs Right Bedroom Vent Before.jpg](#)
9. [Upstairs Office Vent Before .jpg](#)
10. [Dining Area Vent After .jpg](#)
11. [Upstairs Supply Box After .jpg](#)
12. [Work Out Area Vent After .jpg](#)
13. [Front Door Vent Before .jpg](#)
14. [Downstairs Return Before .jpg](#)
15. [Downstairs Return Box After .jpg](#)
16. [Baby's Room Vent After .jpg](#)
17. [Work Out Area Vent Before .jpg](#)
18. [Front Door Vent After .jpg](#)
19. [Dryer Vent Before .jpg](#)
20. [Upstairs Office Vent After .jpg](#)
21. [Upstairs Right Bedroom Vent After .jpg](#)
22. [Upstairs Return Box After .jpg](#)
23. [Upstairs Return Box Before .jpg](#)
24. [Dryer Vent Reading After .jpg](#)
25. [Master Bathroom Vent After .jpg](#)
26. [Upstairs Return Before .jpg](#)
27. [Dryer Vent Hood Before .jpg](#)
28. [Downstairs Supply Box Before .jpg](#)
29. [Dryer Vent Reading Before .jpg](#)
30. [Dryer Vent After .jpg](#)
31. [Master Bedroom Vent Before .jpg](#)
32. [Downstairs Supply Box After.jpg](#)
33. [Living Room Vent Before .jpg](#)
34. [Baby's Room Vent Before .jpg](#)
35. [Downstairs Return After .jpg](#)
36. [Dryer Vent Hood After.jpg](#)