



Weather Master Heating & Air Conditioning Company

Invoice

665433

Invoice Date

11/27/2024

Technician

BWELTE

305 Village Drive
Knightdale, NC 27545

919-266-4415

Remaining Balance

\$0.00

Invoice To

Heidi Balben

705 Hawksbill Drive
Franklinton, NC 27525
508-821-8255 ext.mrs

Location Details

Heidi Balben

705 Hawksbill Drive
Franklinton, NC 27525
508-821-8255 ext.mrs

Work Completed Notes

Lennox
Model:SL280UH090V48B-05
Serial:5920H10468

Arrived due to home inspector saying heat exchanger was covered in rust. after opening up system found that the heat exchanger itself did not have any rust on it. Burner box lid had rust on it from condensation due to hot and cold mixing which is an evitable with furnace being in the attic I cleaned up burn box lid and reinstalled pictures. Attached.

Item Description	Qty		Total
Trip Charge	1x	\$99.00	\$99.00
Clean surface rust off burner box lid, and wipe down the rest of the inside of the furnace	1x	\$50.00	\$50.00
Subtotal:			\$149.00
Discount:			\$0.00
Tax:			\$10.80
Invoice Total:			\$159.80
Paid by CreditCard - 6864:			- \$159.80
Remaining Balance:			\$0.00

Authorization Signature

I authorize the above work to be completed and I agree to pay the above total.

Sam Bann

Payment Signature

I agree that the above work was completed to my satisfaction and I agree to pay the above total.

Sam Bann
