

IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395109 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

***NOTE TO INSPECTIONS DIVISION:** Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC. 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Location & Site Information

Address: 8001 Cornwall Rd Oxford, NC 27565

Subdivision:

Block/Phase: NEW

Lot: 1D

Directions

Road #:

Structure: SINGLE FAMILY

of Bedrooms: 3

of People:

*Water Supply: NEW WELL

System Specifications

Initial System

Usable Soil Depth:

Design Flow: 360

Soil Application Rate: 0.3000

Minimum Trench Depth: 18 Inches

Maximum Trench Depth: 20 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons

Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:
25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:

Soil Application Rate: 0.300

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Minimum Trench Depth: 18 Inches

Maximum Trench: Depth: 20 Inches

Pump Required: ☐ Yes ☒ No ☐ May Be Required

Pump Tank: Gallons

*Proposed System: 25% REDUCTION

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

*Site Modifications

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

*Permit Conditions

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septic area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number P-395109

☒ Improvement Permit

3 bdr m.

☐ Construction Authorization

**SITE SKETCH
ON-SITE / WELL**

Sustainable land

Applicants Name

Walter B. Lewis

Authorized State Agent

8001 Cornwall Rd.

Address

107 ID


Subdivision - Section - Lot

1/5/24

Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.

*EA to be
done once
(house is marked/
layout done in field/
septic area fenced
off)





IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395112 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

*NOTE TO INSPECTIONS DIVISION: Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Location & Site Information

Address: 8007 Cornwall Rd Oxford, NC 27565

Subdivision:

Block/Phase: NEW

Lot: 2D

Directions

Road #:

Structure: SINGLE FAMILY

of Bedrooms: 3

of People:

*Water Supply: NEW WELL

System Specifications

Initial System

Usable Soil Depth:

Design Flow: 360

Soil Application Rate: 0.3000

Minimum Trench Depth: 20 Inches

Maximum Trench Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons

Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:
25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:

Soil Application Rate: 0.300

Minimum Trench Depth: 20 Inches

Maximum Trench Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Pump Required: ☐ Yes ☒ No ☐ May Be Required

*Proposed System: 25% REDUCTION

Pump Tank: Gallons

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

*Site Modifications

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

*Permit Conditions

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septic area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number P-395112

☒ Improvement Permit

360m.

☐ Construction Authorization

**SITE SKETCH
ON-SITE / WELL**

Sustainable Land
Applicants Name


8007 Cornwall Rd.
Address

* lot 2D
Subdivision - Section - Lot

Wesley Wells
Authorized State Agent

1/5/24
Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.



* layout to be
done & have
marked prior
to receiving CA
A system (initial/repair)
to also be permed
off prior



IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395114 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

***NOTE TO INSPECTIONS DIVISION:** Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC. 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Location & Site Information

Address: 8011 Cornwall Rd Oxford, NC 27565

Subdivision:

Block/Phase: NEW

Lot: 3D

Directions

Road #:

Structure: SINGLE FAMILY

of Bedrooms: 3

of People:

*Water Supply: NEW WELL

System Specifications

Initial System

Usable Soil Depth:

Design Flow: 360

Soil Application Rate: 0.3000

Minimum Trench Depth: 20 Inches

Maximum Trench Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons

Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:

25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:

Soil Application Rate: 0.300

Minimum Trench Depth: 20 Inches

Maximum Trench: Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Pump Required: ☐ Yes ☒ No ☐ May Be Required

*Proposed System: 25% REDUCTION

Pump Tank: Gallons

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

*Site Modifications

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

*Permit Conditions

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septic area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number 7-395114

☒ Improvement Permit

☐ Construction Authorization

**SITE SKETCH
ON-SITE / WELL**

Sustainable kind
Applicants Name

804 Cornwall rd.
Address


* lot 30
Subdivision - Section - Lot

Walter B. B. REAS
Authorized State Agent

1/5/24
Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.

* CA to be issued
once house location is
marked / septic area
fenced off / layout
done





IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395115 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

***NOTE TO INSPECTIONS DIVISION:** Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC. 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Location & Site Information

Address: 8015 Cornwall Rd Oxford, NC 27565

Subdivision:

Block/Phase: NEW

Lot: 4D

Directions

Road #:

Structure: SINGLE FAMILY

of Bedrooms: 3

of People:

*Water Supply: NEW WELL

System Specifications

Initial System

Usable Soil Depth:

Design Flow: 360

Soil Application Rate: 0.3000

Minimum Trench Depth: 20 Inches

Maximum Trench Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons

Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:

25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:

Soil Application Rate: 0.300

Minimum Trench Depth: 20 Inches

Maximum Trench: Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Pump Required: ☐ Yes ☐ No ☐ May Be Required

Pump Tank: Gallons

*Proposed System: 25% REDUCTION

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

*Site Modifications

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

*Permit Conditions

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septic area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number P-395115

☒ Improvement Permit

3' berm

☐ Construction Authorization

**SITE SKETCH
ON-SITE / WELL**

Sustainable Land
Applicants Name

8015 Cornwall Rd.
Address


Lot 4D
Subdivision - Section - Lot

Walter O. Lewis
Authorized State Agent

1/5/24
Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.

CA to be done
once house location
marked / septic area
paved off / layout of
system is done





IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395116 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

***NOTE TO INSPECTIONS DIVISION:** Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC. 27565
Phone #: home: (919) 603-4775 cell: (919) 603-4775

Property Location & Site Information

Address: 8019 Cornwall Rd Oxford, NC 27565

Subdivision:

Block/Phase: NEW

Lot: 5D

Directions

Road #:

Structure: SINGLE FAMILY

of Bedrooms: 3

of People:

*Water Supply: NEW WELL

System Specifications

Initial System

Usable Soil Depth:

Minimum Trench Depth: 20 Inches

Design Flow: 360

Maximum Trench Depth: 22 Inches

Soil Application Rate: 0.3000

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons

Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:

25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:

Minimum Trench Depth: 20 Inches

Soil Application Rate: 0.300

Maximum Trench Depth: 22 Inches

*System Classification/Description:

TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Pump Required: ☐ Yes ☒ No ☐ May Be Required

*Proposed System: 25% REDUCTION

Pump Tank: Gallons

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

*Site Modifications

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

*Permit Conditions

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septi area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number 395116

☒ Improvement Permit

☐ Construction Authorization

**SITE SKETCH
ON-SITE / WELL**

Sustainable Land
Applicants Name

801a Cornwall rd.
Address


* lot 5D
Subdivision - Section - Lot

Whitney Bell
Authorized State Agent

11/5/24

Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.



ASCA to be done
once house location
is marked / system laid
out in field / septic area
fenced off

IMPROVEMENT PERMIT

Granville County Health Dept
Environmental Health
101 Hunt Drive
Oxford, NC 27565
Phone: (252) 492-5263 Fax: (252) 492-2361

For Office Use Only

*CDP File Number 395117 - 1
County ID Number: 190800103773
Evaluated For: NEW

PERMIT VALID UNTIL: 03/15/2029

*NOTE TO INSPECTIONS DIVISION: Building Permits cannot be issued with this Improvement Permit.

Applicant: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Owner: Sustainable Land
Address: 3100 Sam Moss Hayes Rd
City: Oxford
State/Zip: NC, 27565
Phone #: home: (919) 603-4775 cell : (919) 603-4775

Property Location & Site Information

Address: 8025 Cornwall Rd Oxford, NC 27565
Road #:
Structure: SINGLE FAMILY
of Bedrooms: 3
of People:
*Water Supply: NEW WELL

Subdivision:

Block/Phase: NEW

Lot: 6D

Directions**System Specifications****Initial System**

Usable Soil Depth:
Design Flow: 360
Soil Application Rate: 0.3000

Minimum Trench Depth: 20 Inches
Maximum Trench Depth: 22 Inches

*System Classification/Description:
TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Septic Tank: 1000 Gallons
Pump Required ☐ Yes ☒ No ☐ May Be Required

*Proposed System:
25% REDUCTION

Pump Tank: Gallons

Repair System Required: ☒ Yes ☐ No ☐ No, but has Available Space

Repair System

Usable Soil Depth:
Soil Application Rate: 0.300

Minimum Trench Depth: 20 Inches
Maximum Trench: Depth: 22 Inches

*System Classification/Description:
TYPE III G. OTHER NON-CONV. TRENCH SYSTEMS

Pump Required: ☐ Yes ☒ No ☐ May Be Required

*Proposed System: 25% REDUCTION

Pump Tank: Gallons

No grading or construction activity is allowed in areas designated for system and repair without approval of Health Department.

***Site Modifications**

The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements.

***Permit Conditions**

CA to be issued once house location marked/System laid out in field/Septic area fenced off. Min. 50' off wells. If there is limited space after house is marked, house may need to be shifted back to accommodate initial/repair area.

PERMIT CONDITIONS WHEN SEPTIC SYSTEM OR REPAIR WILL BE IN FRONT OF HOME

Prior to CA: Erect a 4' tall protection fence along grade line. Septi area is marked on drawing. No grading or construction traffic allowed inside septic area OR PERMIT MAY BE REVOKED.

Septic contractor must meet EHS onsite prior to working on system.

No clearing of trees within area reserved for septic system without prior consultation with EHS.

Utilities shall not cross the drainfield

House gutter and foundation drains shall discharge away from and around area reserved for system and repair.

Granville-Vance Dist. Health Department
Environmental Health

Pin _____

Permit Number P-395117

Improvement Permit

Construction Authorization

360m.
**SITE SKETCH
ON-SITE / WELL**

Sustainable Land
Applicants Name

8025 Cornwall Rd.
Address

* 1st 6D
Subdivision - Section - Lot

[Signature]
Authorized State Agent

11/5/24
Date

System components represent approximate contours only. The contractor must flag the system prior to beginning the installation to ensure that proper grade is maintained.

