

Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsservice@gmail.com

On-site Wastewater Inspection

Property Address: **178 Casei Ln**

Client Name:

Current owner of Record:

Date of Inspection: **1-14-2025**

3 - Advertised number of bedrooms as stated in MLS or as stated in attached sworn statement by owner or owner's representative

360 - Gallons per day for designed system size or number of bedrooms as stated in available local health department information

Inspection shall include any part of the system located more than 5 feet from the primary structure that is a part of the operations permit

Copy of Operations permit from Vance County Environmental Health Attached Operations permit
Available

No - System requires a certified subsurface water pollution control system operator pursuant to G.S. 90A-44

Current Operator's Name - N/A

Location of Septic Tank and septic tank details:

Location: **Beside house on South Side.** Year Installed: **N/A**

10' - ft from house or structure

125' - ft from well if applicable

N/A - ft from water line if applicable and readily visible -

N/A - ft. from property line if said property lines are known

12" - Distance from finished grade to top of tank or access riser

No - Access riser(s)

Yes - Tank lids intact

Yes - Tank has baffle wall

Yes - Inflow to tank is noted as sufficient

Yes - Water level in tank is relative to tank outlet

Yes - Outlet T is present

No - Outlet has filter

Yes - Effluent leaves the outlet

No - Roots present in tank Describe extent of roots:

No - Evidence of tank leakage

No - Evidence of non-permitted connections, such as downspouts or sump pumps

Yes - Connection present from house to tank

Yes - Connection present from tank to next component

Date tank was last pumped 1-14-2025

Does the system have a pump tank? Yes - (complete blanks below)

10' - ft from house or structure

105' - ft from well if applicable

N/A - ft from water line if applicable

N/A - ft from property line if property lines are known

Above grade - Distance from finished grade to top of tank or access riser

Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsservice@gmail.com

Yes - Access risers in place
Concrete - Type of access risers
Good - Condition of tank lids
Beside pump tank riser - Location of control panel
Good - Condition of control panel
Yes - Audible and visible alarms -
Yes - Pump turns on and effluent is delivered to next component

Dispersal field: Type of system: Pump to distribution box & gravel drain field lines.

N/A - ft. from property line if property lines are known
80' - ft from septic/pump tank
5 - # of lines
400' - length of lines
No - Evidence of past or current surfacing at time of inspection
- Evidence of traffic over the dispersal field **Traffic over drain field area, no evidence of damage to drain field at the time of inspection.**
- Vegetation, grading and drainage noted that may affect the condition of the system or system components. **Trees near drain field area, roots could possibly enter drain lines.**
Yes - Effluent is reaching the dispersal field

Conditions present that prevented or hindered the inspection:

Clients should contact Vance County Environmental Health and/or a certified on-site wastewater contractor with questions.

Other pertinent facts noted during inspection:

- Unable to locate distribution box.
- Septic tank lids are marked with orange flags, ends of drain lines are marked with blue flags.
- It is recommended you have your septic tank pumped every 3-5 years.

Inspector Name: Colin Garrett Certification # 7359I

Address 433 Clay Long Rd. Hurdle Mills, NC

Phone 336-583-6111

No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts in place on the date of inspection.

Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsevice@gmail.com

Well Inspection

- No data plate available on the well casing.
- No visible leaks under the well cover.
- Well pump turned on and worked as should.



Septic/pump tank location



Inlet side of septic tank before pumping



Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsservice@gmail.com

Outlet side of septic tank before pumping



Inlet side after pumping



Outlet side after pumping, outlet tee

Baffle wall in septic tank

Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsservice@gmail.com



Inside of pump tank

Control panel

Garrett's Septic Service
Inspector # 7359I
433 Clay Long Rd, Hurdle Mills, NC 27541
336-583-6111 - garrettssepticsevice@gmail.com



Drain field area



Well location



Well casing & pipe head