

3:30 - 3-9-09 Blackley

PERMIT NUMBER 06506

GRANVILLE-VANCE DISTRICT HEALTH DEPARTMENT IMPROVEMENT AND OPERATION PERMITS

COUNTY:	TAX NO.	TYPE OF ESTABLISHMENTS			*THIS PERMIT SHALL BE ACCOMPANIED BY A LAYOUT SHOWN ON A PLAT, INCLUDING SYSTEM REQUIREMENTS.
GRANVILLE	087504409616	RESIDENCE ☒	NUMBER OF BEDROOMS:	NUMBER OF OCCUPANTS:	
OWNER:	SR. NO.	BUSINESS ☐	3	max 6	
RONALD GREGOR	15 South	OTHER ☐	WATER SUPPLY	OTHER	
APPLICANT'S ADDRESS:		Private	WELL ☒	PUBLIC ☐	*THIS IMPROVEMENT PERMIT IS SUBJECT TO REVOCATION IF THE INTENDED USES CHANGE FROM THOSE SHOWN ON THE IMPROVEMENT PERMIT. CHANGES SHALL REQUIRE HEALTH DEPARTMENT APPROVAL.
PO Box 97		TYPE OF WASTEWATER SYSTEM	INITIAL INSTALLATION	REPAIR	
Croodmoor, NC 27522		DESIGN FLOW:	360	360	
PROPERTY ADDRESS/LOCATION:		LTAR:	.30	.30	
155 → (L) on Ravenwood		ABSORPTION AREA:	1200 f. ²	1200 f. ²	
SUBDIVISION:		TRENCH WIDTH:	36"	36"	
Ravenwood		TRENCH DEPTH:	18" high	18"	
LOT NUMBER:		TRENCH SPACING:	9" on center	9" on center	
1		TOTAL TRENCH LENGTH:	400	300'	
REFERENCE SKETCH (SEE PLAT FOR DETAILS)		NUMBER OF TRENCHES:	5-80'		
		GRAVEL DEPTH:	12"	accepted	PERMIT VALID FOR: 5 YEARS YES ☒ NO ☐
		TANK SIZE:	1000 gal		
		PUMP TANK SIZE:	1000 gal		NO EXPIRATION YES ☐ NO ☒
		DISTRIBUTION DEVICE:	Pressure manifold		

keepout on-site
- Maintain contour and level trenches.
- Follow site sketch and pump sheet

***** IMPROVEMENT PERMIT DATE: 9-10-07 *****

FOR: RG Tech Securities
ISSUED BY: Cassette Champion RS

CONSTRUCTION AUTHORIZATION FOR IMPROVEMENT PERMIT# 06506

Unless otherwise indicated, the same conditions above apply regarding system type, layout, location and installation requirements.
(The wastewater system cannot be installed until authorization is signed)

Comments: layout system - install on contour

Date: 9-10-07 Environmental Health Specialist: Cassette Champion RS
Construction Authorization Addendum ☐ Yes ☐ No

OPERATION PERMIT

DATE: 3-9-09 - tent, tanked supply line
3-23-09 pump final

SYSTEM INSTALLED BY: Blackley
ISSUED BY: Cassette Champion RS

PERFORMANCE, MONITORING, MAINTENANCE AND OPERATION
AS REQUIRED BY RULE .1961

Permit Number 6506

✓ Construction Authorization

-Need to determine driveway situation

Ravenwood 101st /
Subdivision - Section - Lot

Physical Address: _____

3-9-09
Date

cut water line in tank under Gasly Chem 69'

buried debris

Authorized Signature

#20

PT

Date _____