

Customer Information

Carrie
120 Carolina Ave
Oxford, NC 27565
USA

RADON CONCENTRATION AVERAGE

1.0 pCi/L

Dear Carrie ,

This is your official report.


The U.S EPA recommended radon action guideline is 4.0 pCi/L. The EPA suggests that you consider taking action to reduce the radon when it is between 2.0 and 4.0 pCi/L. Radon levels can usually be reduced by having a radon reduction (mitigation) system installed in your home or business by a qualified radon mitigation professional. Radon levels in a building can change, so we recommend that you test every 2 years – or sooner if you renovate – even if you mitigate.

If you have any questions about radon or your radon test result, please call or email and we will be happy to answer them.

Best Regards,



Mike Bergmann



Test Results

Average: 1.0 pCi/L

Minimum: 0.5 pCi/L

Maximum: 1.9 pCi/L

Test Information

Start Date: 09/08/2026 08:57 AM EST
End Date: 09/10/2026 11:27 AM EST
Test Duration: 50
Delay: No Delay
Instrument Location: Family Room
Mitigation Tag: 0

Device Information

Device Type: Continuous Radon Monitor
Device Manufacturer: RadonAway
Model: RadStar α310
Serial #: 977
Last Calibration Date: 12/10/2025
Next Calibration Date: 12/10/2026

Tester Information

Started Test: Mike Bergmann
Ended Test: Mike Bergmann

Test Data

Hour	Radon Level (pCi/L)	Alpha Counts	Tilt (T)	Battery (B)	Power (AC)
01	0.4	16			
02	1.4	37			
03	0.7	22			
04	0.7	22			
05	1.2	32			
06	0.8	25			
07	0.9	26			
08	0.6	21			
09	0.7	22			
10	1.1	30			
11	0.6	20			
12	0.9	27			
13	0.5	19			
14	0.9	27			
15	0.8	24			
16	1.2	33			
17	1.1	30			
18	0.9	26			
19	0.9	27			
20	1.4	36			
21	1.0	29			
22	0.7	23			
23	1.2	33			
24	1.6	40			
25	1.9	47			
26	1.7	42			
27	1.4	37			
28	1.3	35			

29	1.4	37
30	1.3	35
31	1.5	38
32	0.8	25
33	0.8	25
34	1.0	28
35	1.0	28
36	0.8	24
37	0.8	24
38	0.8	24
39	0.6	21
40	0.5	19
41	1.0	28
42	0.7	23
43	1.1	30
44	1.0	29
45	0.8	25
46	0.7	22
47	0.6	20
48	0.5	19
49	0.6	20
50	0.6	20

Test Results

Average: 1.0 pCi/L

Minimum: 0.5 pCi/L

Maximum: 1.9 pCi/L

Photos




Photo 1

Radon