

Property Condition Report

Case Number: 387-585129 Current Step: 1c-Ready to Show Condition Step Date: 03/31/2026 HOC: Atlanta	Contract Area: 5A Address: 610 S WAKEFIELD ST City, St Zip: ZEBULON, NC 27597-0000
--	---

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	OK	HVAC tested and functional?:	Yes	Generator
--Heating/Furnace:	OK			
--HVAC System Duct:	OK			
Electrical Wiring:	OK	Electric supply tested and functional?:	Yes	Generator
--Other:	OK			
--Other:	OK			
Stove/Range/Oven:	OK	Built-in appliances tested and functional?:	Yes	Generator
--Kitchen Cabinets:	OK			
--Other:	OK			
Plumbing:	OK	Water supply tested and functional?:	Yes	pressure test pass
--Sink:	OK			
--Other:	OK			
Water Heater:	OK	Water heater functional?:	Yes	visual pass
Sewer/Septic System:	OK	Sanitary & plumbing system functional?:	Yes	water in drains pass
--Toilet:	OK			
--Other:	OK			
Roof:	OK	Roofing in acceptable condition?:	Yes	visual pass
--Other:	OK			