



Indoor Environmental Systems, Inc.

Healthy Home Service 2022

Date



5128 Pinehall Wynd



Crawlspace looks good and is performing well!



The subfloor was checked—no signs of mold.



Indoor Environmental Systems, Inc.

Healthy Home Service 2022



Filtered Fresh Air Ventilation System was cleaned. A new carbon filter was installed & 3 new filters were left for you.





Indoor Environmental Systems, Inc.

Healthy Home Service 2022



Before



Bug sticky plates were removed & new ones were placed throughout the crawl space.



The supply vent was checked – your crawl space is nice and dry!



The attached distribution box was checked—looks clean.



Indoor Environmental Systems, Inc.

Healthy Home Service 2022



The air handler unit coil was cleaned & sanitized.





Indoor Environmental Systems, Inc.

Healthy Home Service 2022



An interesting thing was found—the sump pump bucket had lifted out of the ground. The guys pulled back the moisture barrier, put it back in the ground and repaired the moisture barrier. Good as new!