

Sprinkler System Inspection

TRC Global Mobility
7270 S 13th Street Suite 201
Oak Creek, WI 53154

05/19/2026
Client File # 17459-3260
FICS File # 3063493

Inspection Address

Nathan Schalk
2608 Historic Circle
Morrisville, NC 27560

In accordance with your request a Sprinkler Inspection was conducted on **05/19/2026** at the above captioned property. All visible components of the 7 zone sprinkler system were evaluated. The following is a summary of the inspector's findings.

CONDITION OF COMPONENTS	
Automatic Timer	Could not test as the unit is controlled by bluetooth and user access is available at this time.
 Remote control panel in garage	
Manual Controls	Not Present
Shut Off/Draining Valves	See above
Individual Zones/Pop up Heads	The system was found to be disconnected from the water supply and could not be tested.
Water Pressure Flow	See above

If you should have any questions, please do not hesitate to contact me.

Sincerely,



Frank Winiowski Jr.
Director of Account Management