

System:
Repair:
Soil Profiles: #1

Repair: Subsurface Drip
Lines: (>800')
0.15 LTAR
6" Trench Bottom



Septic System Layout
(System)
Lot 78 Lake Anne Subdivision
Raleigh, Wake County
North Carolina

Job# : 2272
Drawn By : JH & MB
Date : 00/00/0000
Revision: 09/11/2026