Current Operator's Name _____
Most recent performance, operation and maintenance reports are ____attached ____not available
Type of water supply X Well____ Public Water ____Community Water ____Spring
Location of Septic Tank and septic tank details:
15 ft from house or structure
100 ft from well if applicable
UkN ft from water line if applicable
UkN ft. from property line if said property lines are known or marked Property lines not marked
UkN distance from finished grade to top of tank or access riser
r(s) yes no Describe Metal pipe, open + no lid
ıtact yes no
affle wall yes no Describe condition of baffle wall: _____
ank is noted as sufficient
UkN Inflow to tank is noted as insufficient or blocked
NO Water level in tank is relative to tank outlet
UkN Outlet T is present yes no Describe condition of Outlet T: _____
UkN Outlet has filter yes no Describe condition of filter: _____
UkN Effluent leaves the outlet yes no
Yes Roots present in tank yes no Describe extent of roots: Mats of roots in the tank
NO Evidence of tank leakage Describe: _____
NO Evidence of non-permitted connections, such as downspouts or sump pumps
Yes Connection present from house to tank
UkN Connection present from tank to next component
UkN Percentage of solids in tank
NO Unable to locate tank. System inspection cannot be completed until tank is located

Date tank was last pumped _____ unknown

Does system have pump tank? ~~yes~~ (complete blanks below) NO na

____ ft from house or structure
____ ft from well or spring if applicable
____ ft from water line if applicable
____ ft. from property line if property lines are known or marked
____ Distance from finished grade to top of tank or access riser

Pump Tank Observations Continued:
____ Access risers in place yes no
____ ft from septic tank
____ Access risers in place Describe type: _____
____ Describe condition of tank lids _____
Location of control panel: _____
____ Electrical connections are in place and properly grounded
____ Audible and visible alarms (as applicable) work
____ Pump turns on and effluent is delivered to next component
____ Unable to operate pump due to lack of electricity at site at time of inspection
Dispersal field: Type of system: X Conventional ___Accepted ___Innovative ___Experimental __Controlled Demonstration ___Pretreatment; Type of pretreatment _____
Brief Description of System Type II A
UkN ft. from property line if property lines are known or marked
UkN ft from septic/pump tank
UkN # of lines
UkN length of lines
NO Evidence of past or current surfacing at time of inspection
Briefly describe: _____
NO Evidence of traffic over the dispersal field
~~Yes~~ Yes Vegetation, grading and drainage noted that may affect the condition of the system or system components
UkN Effluent is reaching the dispersal field
Yes Conditions present that prevented or hindered the inspection
Yes Adverse conditions present that require repair or subsequent observation or warrants further evaluation by the local health department. Description of adverse condition: The tank is collapsing + full of roots

Consequences of the adverse condition: The tank will collapse leaving a open hole which is a saftey hazard.

Client should contact Wake County Environmental Health and/or a certified on-site wastewater contractor
Other pertinent facts noted during inspection: Found a metal pipe sticking up that was concreted around it to the tank. Probed around it & the probe went through the metal lid. Used the camera down the pipe to get pictures of inside the tank + found the metal lids rusted + bowed. There was no water in the tank, + roots in the tank. Unable to locate the drainfield. Should contact Wake County Environmental Health for a repair.

Inspector Name: Jack B. Durham, Jr. Certification # 2462 I
Address 2021 Sandy Plains Rd., Wake Forest, NC 27587
Phone 919-451-5377
No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of the onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts in place on date of inspection.

Inspector Signature: William H. Durham #6602 I Date 10-19-06