First Choice R & R Radon Remediation
5100 Unicon Dr
Suite 105
Wake Forest, NC 27587
info@firstforradon.com | 984-867-2366

Customer Information

Kyle Soffe
1842 Piney Falls Dr
Wendell, NC 27591
USA

RADON CONCENTRATION AVERAGE

< 0.5 pCi/L

Dear Kyle Soffe,

Best Regards,



Randy Paquette

All 47 lower states

103873 RMT FAFM ART
NC general 36543

First Choice R & R Radon Remediation
5100 Unicon Dr
Suite 105
Wake Forest, NC 27587
info@firstforradon.com | 984-867-2366



Test Results

Average: < 0.5 pCi/L **Minimum:** 0.0 pCi/L **Maximum:** 0.9 pCi/L

Test Information

Start Date:	03/15/2024 09:34 AM EST
End Date:	03/18/2024 09:35 AM EST
Delay:	No delay
Instrument Location:	Main floor
Mitigation System Present:	AsdOperating

Device Information

Device Type:	Continuous Radon Monitor
Device Manufacturer:	RadonAway
Device Model:	RadStar RS300
Serial #:	03603
Calibration #:	29000 Bkgnd04
Last Callibration Date:	12/19/2024
Next Callibration Date:	12/19/2025

Tester Information

Started Test:	Randy Paquette All 47 lower states
Ended Test:	Randy Paquette All 47 lower states



First Choice R & R Radon Remediation
5100 Unicon Dr
Suite 105
Wake Forest, NC 27587
info@firstforradon.com | 984-867-2366

Test Data

Hour	Radon Level (pCi/L)	Alpha Counts	Tilt(T)	Battery (B)	Power (AC)
01	**0.2**	**5**			
02	**0.2**	**3**			
03	**0.0**	**0**			
04	**0.4**	**9**			
05	**0.2**	**3**			
06	**0.4**	**9**			
07	**0.2**	**5**			
08	**0.0**	**0**			
09	**0.2**	**4**			
10	**0.1**	**2**			
11	**0.5**	**11**			
12	**0.5**	**10**			
13	**0.6**	**13**			
14	**0.3**	**7**			
15	**0.3**	**6**			
16	**0.7**	**14**			
17	**0.8**	**17**			
18	**0.2**	**5**			
19	**0.5**	**11**			
20	**0.9**	**18**			
21	**0.5**	**11**			
22	**0.5**	**10**			
23	**0.3**	**7**			
24	**0.6**	**13**			
25	**0.3**	**6**			
26	**0.5**	**10**			
27	**0.7**	**15**			
28	**0.2**	**4**			
29	**0.3**	**7**			



First Choice R & R Radon Remediation
5100 Unicon Dr
Suite 105
Wake Forest, NC 27587
info@firstforradon.com | 984-867-2366

30	**0.5**	**10**
31	**0.3**	**6**
32	**0.5**	**11**
33	**0.2**	**5**
34	**0.7**	**15**
35	**0.6**	**12**
36	**0.5**	**11**
37	**0.4**	**9**
38	**0.4**	**9**
39	**0.4**	**8**
40	**0.6**	**13**
41	**0.5**	**10**
42	**0.4**	**9**
43	**0.5**	**11**
44	**0.7**	**14**
45	**0.8**	**16**
46	**0.1**	**2**
47	**0.6**	**12**
48	**0.4**	**8**
49	**0.4**	**8**
50	**0.4**	**9**
51	**0.4**	**8**
52	**0.2**	**4**
53	**0.0**	**0**
54	**0.6**	**12**
55	**0.2**	**4**
56	**0.4**	**9**
57	**0.4**	**9**
58	**0.2**	**5**
59	**0.0**	**1**
60	**0.7**	**14**
61	**0.4**	**8**
62	**0.6**	**12**
63	**0.3**	**7**



First Choice R & R Radon Remediation
5100 Unicon Dr
Suite 105
Wake Forest, NC 27587
info@firstforradon.com | 984-867-2366

64	**0.3**	**6**
65	**0.2**	**5**
66	**0.5**	**11**
67	**0.6**	**12**
68	**0.3**	**6**
69	**0.4**	**8**
70	**0.2**	**4**
71	**0.0**	**1**
72	**0.0**	**0**

Test Results

Average: < 0.5 pCi/L **Minimum:** 0.0 pCi/L **Maximum:** 0.9 pCi/L